



Dual Frog Juicer and BD20 Occupancy Detectors on Lower Loop





Part of the isolating part of the return loop. This is located under the 1L lift off sectionsSection of track under the lift off

Note : There was a **problem with the circuit**. After much investigation this was found to be because the soldering of one track over the rail join between 1L and 5L (loop to store in) had joined up, thus creating a short circuit. **It was resolved by melting a bit of solder.**
May 2025

